



Front of Vincent
Station



Front Entrance



Front Section of
Engine Bays



Radio Room
Window



Radio Room



Top Front of Engine
Bays



Broken Window in
Dormitory



Broken Window in
TV Room



Ceiling Damage
Foyer



Ceiling Damage
Passage



Ceiling Damage TV
Room



Ceiling Damage
Dormitory



Engine Bay Doors
Cable Missing



Engine Bay Roof



Roof structure
Vincent Station